



DOCKET NO.: 0506-1035  
APPLN NO.: 09/079,949  
REPLY TO NOTICE OF ALLOWABILITY OF: FEBRUARY 10, 2005  
REPLACEMENT SHEET




Figure 1



DOCKET NO.: 0508-1035  
 APPLN NO.: 09/879,949  
 REPLY TO NOTICE OF ALLOWABILITY OF: FEBRUARY 10, 2005  
 REPLACEMENT SHEET

Transverse Cross-Section of the Catheter





Figure 2

Transverse Cross-Section of the Catheter



DOCKET NO.: 0508-1035  
 APPL. NO.: 09/879,849  
 REPLY TO NOTICE OF ALLOWABILITY OF: FEBRUARY 10, 2005  
 REPLACEMENT SHEET

Figure 3